




Note: Figure provided by Seattle Public Utilities


Figure 1 - Vicinity Map: South lot of Northgate Mall




Note: Figure provided by Seattle Public Utilities

Figure 2 - Sub-basins draining to Daylight Alternative

Note: Figure provided by Seattle Public Utilities



A) NDS 1 – treats runoff from approximately 99 acres of contributing area



B) NDS 2 – treats runoff from approximately 86 acres of contributing area

Figure 3 - Sub-basins draining to Natural Drainage System Alternative

Note: Figure provided by Seattle Public Utilities






Figure 4 - Sub-basins draining to Hybrid Alternatives



Note: Figure provided by Seattle Public Utilities

Figure 6 Sub-basin draining to Water Quality Monitoring Site

Average and Peak Daily Flows – Data Provided by SPU
Monitoring Period 12-01 to 5-02



Water Quality Data – Data Provided by SPU
Monitoring Period 12-01 to 5-02




Figure 7 – Flow and Water Quality Data from Water Quality Monitoring Site




Figure 8 - TSS and Total Zn Removed per Year and per Acre per Year for Method A




Figure 9 - TSS and Total Zn Removed per Year and per Acre per Year for Method B